


1.	Nomenclature/Part No/ GIG Number	Actuating Unit/ BI-2A/798854
2.	Year of Production/Source	AVIAZAPCHAST PLC(AHQ/441)
3.	Fleet/Sub System/Wpn system	An-32
4.	Technical Applicability/Broad Purpose	Aircraft Fire Extinguisher system
5.	Technical Specifications	
6.	Publication Details (attach as separate sheets)	IPC 026.11.00 ITEM 16 FIG 1 PAGE 4
7.	Photograph of equipment	
8.	Brief Description	The aggregate is actuating unit of aircraft fire extinguishing system. The LRU controls the actuation of fire bottle on sensing the fire alarms and provides indication in cockpit.
9.	Classification of equipment-LRU/Testers/Ground equipment/Role equipment, Electrical, Electronics, Mechanical, Software based etc.)	Rotable
10.	Previous Repair History	Aggregate is Obsolete and being replaced with BPS-32 system. Not Required.
11.	Criticality (Priority I, II or III)	N/A
12.	Requirement: Repair or Indigenization or both?	Indigenization
13.	Quantity Required (One time/Annual)	15
14.	Sample Applicability	Sample available
15.	Scale/Deficiency	scale 101/Cat D 195/ Def-nil
16.	If deficient- How deficiency is being plugged?	Cannibalisation
17.	SPOC details item/fleet wise	SPE ISC, 1 BRD, AF

18.	Draft QTS with major testing requirement (If already designed)	(To be generated by vendor in consultation with RCMA
19.	Any Other Relevant Information	

КАТАЛОГ ЛІТАЛІЎ І
СБОРОЧНЫХ ЕДИНІЦ

ANTONOV®
AN-32RE




Рис. 1. УСТАНОВКА БЛОКОВ БМ-2А ССП-75ИС А03-20 МЕЖДУ ШТАНГОУ
ПОДРАЗДЕЛОМ ПО УСТАНОВКЕ БЛОКА БМ-2А