

NGV STAGE III

1. Nomenclature/ Part No/ GIG No- NGV Stage-III / 078046.2980-02 /1541076
2. Year of Procurement/ Source .-2018/ Motor Sich
3. Fleet/ Sub System/Wpn System .MI-17/ TV3-117MT A/E
4. Technical Applicability/ Broad Purpose. Intended to direct the airflow of hot gases on FT 1St Rotor.
5. Technical Specifications (attach as separate sheets) .N/A
6. Publication Details (attach as separate sheets). Attached
7. Photograph of Equipment . Annexed
8. Brief Description .Item is fitted in 2ND Housing and also works as housing 3RD support bearing bore.
9. Classification of Equipment- LRU/Testers/ Ground Equipment/ Role Equipment :- (Electrical, Electronics, Mechanical, Software based etc.). Mechanical
10. Previous Repair History. Welding carried out on struts and walls as per TEC.
11. Criticality (Priority I, II or III).Priority I
12. Requirement: Repair or Indigenisation or both? Both
13. Quantity Required (One time/ Annual) . Annually 08
14. Sample Availability .Cat 'E'
15. Scale/ Deficiency . /06
16. If deficient - How deficiency is being plugged? from rearline aero engines
17. SPOC details item/ fleet wise. **SPE (IDS)**
18. Draft QTS with major testing requirement (If already designed) N/A
19. Any Other Relevant Information. N/A

